Design Graphics – MECH 289

Assignment CAD1
Handed out January 29, 2007   Due February 9, 2007

Create the solid models both in Pro/Engineer and SolidWorks, using the dimensions
shown below. From both s/w packages printout the models in wireframe modes with
hidden lines shown, and all dimensions shown. All dimensions are given in mm.

Print using Print Screen option (Prt Scr button) together with the Pro/E and SolidWorks
frames.