





O(0,0,0)
M(14,6,4.5)



(GC2) Generate the transition piece development.

Use technique outlined
on pp.53-55 of ...



... /~paul/M2DG289LC.pdf